ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0253	NA	Jayanna Layout
Segment No.	**Total Length (m)**	
1/S-W0253/S025942	223.73	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	223.73	77.605871	13.104407	77.605799	13.102386	RI-A07	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Drains at Jayanna Layout in ward no 01 Yelahanka Sub-Division Yelahanka zone	1990000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	
Tender	Construction of Drains at Jayanna Layout in ward no 01 Yelahanka Sub-Division Yelahanka zone	**Job No. / Work Code** 001-16-000012
Work Order No.	**Work Order Date**	**Period of Extention**
EE(YNK.D)/E-PMT-1/WO/02/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/02/2016	23/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
T K SHANKARAPPA		0.00
Phone No.	**E-Mail ID**	
9964440879		

Field Inspection Details

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0253

Date: 03/12/2016 **Time:** 15:09:19 RH20161203150919

Number of Trees

4

Any Other Information

Name

CHANDRASHEKAR

Date of Inspection

03/12/2016

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	VASU K M	03/12/2016	02/01/2017	COMPLETED
AEE	G.B. PRABHAKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0253

Date: 03/12/2016 **Time:** 15:09:19 RH20161203150919